



Paints required:




(N5-X011 by Number Five)



(N5-X070 by Number Five)





deca_[Cas]



3D resin is fragile, so you should NOT use excessive force when removing the supports or joining the pieces or you risk breaking the parts.

Carry out a test assembly before painting the parts, sanding where necessary and preferably the plastic parts of the kit, until the parts fit together with light pressure without being forced.

gondabox.co 30 design